

SUBJECT: Part number change for particular Position Sensor from the EVA-W7 product family

BULLETIN #: ECN. PG45.03.21.06-4

Date: March 21, 2006

Page 1 of 1

EFFECTIVE DATE: March 21, 2006

LAST ORDER DATE: April 30, 2006

LAST SHIPMENT DATE: May 31, 2006

REASON FOR CHANGE:

Replacement part has shorter operating life of 20K cycles due to change in metal cover material.

AFFECTED PART NUMBERS: EVA-W7LR04B34

REPLACEMENT: EVA-W7NR04B34

PRODUCT DATASHEET:

<http://panasonic.com/industrial/components/pdf/AOL0000CE13.pdf>