

SUBJECT: Power Choke Coil ETQ-P5LxxxXFA Manufacturing Location Change

BULLETIN #: ECN.PG47.03.17.06-2a

Date: March 17, 2006

Page 1 of 1

EFFECTIVE DATE: May 1, 2006

REASON FOR CHANGE: More Cost-Effective Manufacturing Capability

ENGINEERING CHANGE DETAILS:

Manufacturing changed from Japan (Tajima, 106) to Singapore (PEDSG, 75)

NOTES:

Part Number valid with or without the 'dash' / ' - '

Part Numbers Presently Affected:

ETQ-P5LR50XFA

ETQ-P5LR60XFA