

SUBJECT: Push-type power switches are now not recommended for new design.

BULLETIN #: NRFND.PG45.10.16.06-1

Date: October 16, 2006

Page 1 of 1

EFFECTIVE DATE: October 16, 2006

RECOMMENDED REPLACEMENT: None.

OTHER DETAILS: Discontinuation is planned for December 2007. Market demand for power switches has diminished due to the rise of LCD / Plasma TVs taking share from traditional CRT-type TVs, the primary application for power switches.

AFFECTED PART NUMBERS:

ESB-92S\*\*\*, ESB-92D\*\*\*.