

**SUBJECT: Slide switches are not recommended for new designs**

**BULLETIN #:** NRFND.PG45.10.17.07-1

**Date:** October, 17 2007

**Page 1 of 1**

**EFFECTIVE DATE: October 31, 2007**

**RECOMMENDED REPLACEMENT: No replacement due to lack of demand.**

**OTHER DETAILS: Not recommended for new design due to lack of demand and planned discontinuation in Q4 2008.**

**AFFECTED PART NUMBERS:**

**2mm Slide Switches ESD-16\*\*\*,  
3mm Slide switches ESD-11\*\*\*,  
5mm slide switches ESD-17\*\*\*.**

**PRODUCT DATASHEET:**

<http://panasonic.com/industrial/components/pdf/ATG0000CE16.pdf>

<http://panasonic.com/industrial/components/pdf/ATG0000CE17.pdf>

<http://panasonic.com/industrial/components/pdf/ATG0000CE18.pdf>