

SUBJECT: Motor-Driven Slide Potentiometer series is not recommended for new designs

BULLETIN #: NRFND.PG45.11.03.05-1

Date: November 3, 2005

Page 1 of 1

EFFECTIVE DATE: November 3, 2005

RECOMMENDED REPLACEMENT: No replacement due to lack of demand.

OTHER DETAILS: 60mm/100mm vertical motor-driven slide potentiometers (faders).

AFFECTED PART NUMBERS: EVA-NQ*, EVA-NR*, EVA-NC*, EVB-NC*