



**SUBJECT : DISCONTINUED PRODUCT NOTIFICATION**  
**EVQ Light Touch Switches**

**EVQ Light Touch Switches**  
**PRODUCT NEWS**

DATE : Dec.24,1998  
Bulletin # : EMD981224-1

The EVQ Light Touch Switches described the below will be DISCONTINUED EFFECTIVE DECEMBER 31, 1999

EVQPFCxxx	5N Type LTSW Side-push Type
EVQPFDxxx	5N Type LTSW Side-push Type
EVQQHPxxx	Surface Mount LTSW with Knob for Reflow Soldering
EVQQHUxxx	Surface Mount LTSW with Knob for Reflow Soldering
EVQQHVxxx	Surface Mount LTSW with Knob for Reflow Soldering
EVQPME05Q	6mm Square Long Travel LTSW
EVQPMY05K	6mm Square Long Travel LTSW

**SUGGESTED REPLACEMENT**

( Current P/N )	( Replacement P/N)
EVQPFCxxx	<u>EVQPF0xxx</u>
EVQPFDxxx	<u>EVQPF1xxx</u>
EVQQHPxxx	<u>EVQQWPxxx</u>
EVQQHUxxx	<u>EVQQWTxxx</u>
EVQQHVxxx	<u>EVQQWSxxx</u>
EVQPME05Q	<u>EVQP1D05M</u>
EVQPMY05K	<u>EVQP1B05M</u>

Please notify your present customers of this change and the recommended replacement series'.  
Please note the PC board layout is slightly different when changing to the Replacement P/N. Please contact the EMC Resident engineers with any technical questions.