

SUBJECT: Part number change for particular Detector Switch from the ESE-21 product family.

BULLETIN #: ECN. PG45.03.21.06-2

Date: March 21, 2006

Page 1 of 1

EFFECTIVE DATE: March 21, 2006

LAST ORDER DATE: April 30, 2006

LAST SHIPMENT DATE: May 31, 2006

REASON FOR CHANGE:

Improved feedback force characteristic for the 2NV super small size Detector Switch.

AFFECTED PART NUMBERS: ESE-2101BT

REPLACEMENT: ESE-2121BT

PRODUCT DATASHEET:

<http://panasonic.com/industrial/components/pdf/ATB0000CE3.pdf>